ECS Configuration Change Request Page 1 of 1 Pages							
CCR No.	96-0880	Logged Date	7/31/96	Rev	Request Ty	ype CCR	
Priority	Routine	Urgent X E	Emergency	Affected Release	С	Change Class	II
Title Request for support to install DirecPC on the PC located in room 1028.							
Documents Affected				Source Nos (RID, NCR, Action Item, GSFC CCR, etc.) or Tech Reference			
RTM Change Start New Baseline							
Problem Need to install DirecPC system which includes a 21" fiberglass dish, ISA adapter card, and software to implement an evaluation for the ECS Transfer Technology Testbed in room 1028.							
Proposed Solution Request for HTSC to install the ISA adapter card, and software that has been purchased, and approved to be used on the host machine. The host machine is a Micron Pentium running Windows 3.1. Request for facilities to install the dish antenna.							
Impact Analysis:							
•	ons Affected:	B00 _	Contracts	ESO	FOS L	M&O	
QA A 1	Rel. A	Rel. B	Rel. IR1	MRS	SMO X	Subconts	Ш
A.1 Cost:	Other Re	None	Small	X Me	dium 🗍	Large	<u> </u>
		<u>—</u>	(Not exceeding	\$100,000) (\$100,0	000 to \$500,000)	(Over \$50	00,000)
Sched		None	Other				
	nal LOC			Man-Month	s		
Materia	als						
Originator Christopher Minor Signature Date							
Office SER	C Office	Manager	gnature			Date	
Dispositio	<b>n</b> Approve		proved w/Comm	ent Forw	ard	Disapproved	$\frac{1}{\Box}$
Comments			•				

CM01JU96 ECS

Date

Signature

CCB Chairperson